

20190406 DO NOTAM TDFM Best Practices

Mission Pilots should follow these practices on every flight:

1. Attempt to make radio contact with any Beaver Fox (BF) station after engine start up. If no contact, then make a second attempt after airborne. If no contact, no further attempts are required. If flying multiple sorties in one day you need only attempt radio contact on the first sortie.
2. Ensure you're monitoring CAP Guard in case we need to contact you and redirect for a mission.